VILLAGE OF TUXEDO PARK

P.O. BOX 31 80 LORILLARD ROAD TUXEDO PARK, NEW YORK 10987

> Building Inspector Summary Report January 22, 2013

1. Building Permits

a. Schmidtberger, 21 Cannon Hill Rd., Potting Shed

2. Inspections

- a. Zgonena, Tower Hill Rd. Inspected property with owner's engineer, David Higgins from Lanc & Tully.
- b. Niblo, Cliff Rd. Framing
- c. Urmansky, Tuxedo Rd. Removal of trees from property by Ira Wicks.
- d. Tuxedo Club Boathouse, Tuxedo Rd. Footings and foundation walls.
- e. Hanson, Tower Hill Rd. Storage shed footings
- f. Dow, (Boathouse) Chastellux Lane Reset stone that shifted during the hurricane.
- g. Perez, Walked property with property owner and identified trees that needed to be removed.
- h. VTP Police Station, Removal of wires above Tuxedo Rd.

3. Correspondence/Project Updates

- a. Yankee Propane Removed old propane tanks not in use from 54 West Lake Stable Rd.
- b. Sent letters regarding tree removal to:
 - 1. Pendl, Ridge Rd.
 - 2. Xu, Tuxedo Rd.
 - 3. Perez, Tuxedo Rd.
 - 4. Tuxedo Park Estates, Tuxedo Rd.
- c. King, Clubhouse Rd. Issued Certificate of Occupancy (Seasonal Use May Sept).
- d. Requested help from Tuxedo Chase Bank Branch Manager, Sandra Davis, to have Chase cleanup 3 Acoma Rd. (Isaac Levenbrown).
- e. Sent letter to the Niblo's regarding framing not complying with the plans.
- f. Contacted Verizon regarding removal of utility poles behind Village Office, Tower Hill Loop, and Tuxedo Rd. Work since completed.
- g. Contacted Patrick Bourke and Tamer El-Rayess regarding alternative methods of operating the South Gate when telephone and internet services are down. Referred to contact Thomas Butler, Homeworks Group. Sent email and left voicemail to set up meeting ASAP.
- h. Contacted Orange & Rockland regarding:
 - 1. Inoperative street lights.
 - 2. Removal of electrical meter and service pole from former Police Dept. building.
- i. Coordinating removal of small sheds from South Gate House and Main Gate areas to prepare for spring cleanup.
- j. Yaboo Fence Sent request that the proposed bill be adjusted to reflect similar work performed approximately one year ago.
- k. Water Loss Analysis as of December 2012 billing (62% loss).

BUILDING DEPARTMENT - APPLICATION/PERMIT VILLAGE OF TUXEDO PARK-LORILARD ROAD-TUXEDO PARK, N.Y. 10987 845-351-4745

PROPERTY LOCATION - SECTION 104 BLOCK LOT 1.3
OWNER: Schmidtberger PROPERTY STREET ADDRESS CANNON HILL
MAILING ADDRESS ZOI E, 80 mst. Aptgf. Ny Ny 10075 TELEPHONE 914-715-9659
NATURE OF CONSTRUCTION NEW ALTERATION ADDITION RECONSTRUCTION
ACCESSARY USEOTHER-DESCRIBE
IF STRUCTURE BRIEF DESCRIPTION POTTING SHED
ESTIMATED COST OF CONSTRUCTION 450,000
THE OWNER/AGENT IS THE OWNER OR AGENT OF ALL THAT CERTAIN LOT, PIECE OR PARCEL OF LAND AND OR BUILDING DESCRIBED IN THE APPLICATION AND IF NOT THE OWNER THAT HE HAS BEEN DULY AND PROPERLY AUTHORIZED TO MAKE THIS APPLICATION AND TO ASSUME RESPONSIBILITY FOR THE OWNER IN CONNECTION WITH THIS APPLICATION AND AGREES THAT THE VILLAGE OF TUXEDO PARK ZONING ORDINANCE AND STATE OF NEW YORK BUILDING CODES WILL BE COMPLIED WITH AS WELL AS ANY OTHER REGULATIONS RELATING TO THE CONSTRUCTION OR USE OF THE PROPOSED BUILDING AND LAND HERE IN DESCRIBED JOHN C. LEDWITH IV
N.Y.Scoregistres by Crange County Preused Engineer Name
ADDRESSTELEPHONE
BUILDING OR CONTRACTOR SAB TOTAL HOME CARE INC.
ADDRESS <u>BOBOK</u> 437 TELEPHONE <u>845-781-745</u>
BUILDERS INSURANCE INFORMATION: WORKMENS COMPENSATION #
LIABILITY #
AGENT OR COMPANY
AGENT OR COMPANY
AGENT OR COMPANY ADDRESS
AGENT OR COMPANY ADDRESSTELEPHONE VILLAGE CLERK: DATE RECEIVED NOV. ZO ZOIL FEE PAID AP ZOO Escrolo 3000
AGENT OR COMPANY ADDRESS
AGENT OR COMPANY ADDRESS TELEPHONE VILLAGE CLERK: DATE RECEIVED NOV. ZO ZOIC FEE PAID AP ZOO Escroti 3000 BUILDING INSPECTOR: PRELIMINARY INSPECTION— APPROVED DISAPPROVED DATE 1/4// COMMENTS BOARD OF ARCHITECTURAL REVIEW: APPROVED DISAPPROVED - DATE 1/15/13 SIGNATURES Chambers AHRB. COMMENTS
AGENT OR COMPANY ADDRESS TELEPHONE VILLAGE CLERK: DATE RECEIVED NOV. ZOZOIC FEE PAID AP ZOO Escolo 3000 BUILDING INSPECTOR: PRELIMINARY INSPECTION— APPROVED DISAPPROVED DATE //// S COMMENTS BOARD OF ARCHITECTURAL REVIEW: APPROVED DISAPPROVED - DATE 1/15/13 SIGNATURES APPROVED DISAPPROVED DATE BOARD OF TRUSTEES: APPROVED DISAPPROVED DATE
AGENT OR COMPANY ADDRESS TELEPHONE VILLAGE CLERK: DATE RECEIVED NOV. ZO ZOIC FEE PAID AP ZOO Escroti 3000 BUILDING INSPECTOR: PRELIMINARY INSPECTION— APPROVED DISAPPROVED DATE 1/4// COMMENTS BOARD OF ARCHITECTURAL REVIEW: APPROVED DISAPPROVED - DATE 1/15/13 SIGNATURES Chambers AHRB. COMMENTS
AGENT OR COMPANY ADDRESS TELEPHONE VILLAGE CLERK: DATE RECEIVED NOV. ZO ZOIL FEE PAID AP ZOO Escroll 3000 BUILDING INSPECTOR: PRELIMINARY INSPECTION— APPROVED DISAPPROVED DATE //// COMMENTS BOARD OF ARCHITECTURAL REVIEW: APPROVED DISAPPROVED - DATE ///// SIGNATURES AHRB. COMMENTS BOARD OF TRUSTEES: APPROVED DISAPPROVED DATE SIGNATURES SIGNATURES
AGENT OR COMPANY ADDRESS TELEPHONE VILLAGE CLERK: DATE RECEIVED NOV. ZO ZOIL FEE PAID AP ZOO Escoll 3000 BUILDING INSPECTOR: PRELIMINARY INSPECTION— APPROVED DISAPPROVED DATE 1/4/3 COMMENTS BOARD OF ARCHITECTURAL REVIEW: APPROVED DISAPPROVED — DATE 1/5/3 SIGNATURES AHRB. COMMENTS BOARD OF TRUSTEES: APPROVED DISAPPROVED — DATE SIGNATURES TRUSTEES COMMENTS: I HAVE EXAMINED THIS APPLICATION AND THE PLANS (BUILDING AND PLOT) THAT ARE A PART OF THIS APPLICATION AND FIND THAT THEY ARE IN COMPLIANCE WITH THE VILLAGE OF TUXEDO PARK ZONING ORDINANCE AND HEREBY ISSUE THIS BUILDING PERMIT.
AGENT OR COMPANY ADDRESS TELEPHONE VILLAGE CLERK: DATE RECEIVED NOV. 20 201 FEE PAID AD 200 Escape 200 BUILDING INSPECTOR: PRELIMINARY INSPECTION— APPROVED DISAPPROVED DATE //// COMMENTS BOARD OF ARCHITECTURAL REVIEW: APPROVED DISAPPROVED - DATE /// S SIGNATURES AHRB. COMMENTS BOARD OF TRUSTEES: APPROVED DISAPPROVED DATE SIGNATURES TRUSTEES COMMENTS: I HAVE EXAMINED THIS APPLICATION AND THE PLANS (BUILDING AND PLOT) THAT ARE A PART OF THIS APPLICATION AND FIND THAT THEY ARE IN COMPLIANCE WITH THE VILLAGE OF TUXEDO PARK ZONING ORDINANCE AND HEREBY ISSUE THIS BUILDING

John Ledwith

From: David Higgins [deh@lanctully.com]

Sent: Wednesday, December 26, 2012 2:29 PM

To: jledwith@tuxedopark-ny.gov cc: rzgonena@gmail.com

Subject: Zgonena Property- Tower Hill Road

Attachments: zgonena memo 12-26-12.pdf; IMG_0707-rev.JPG; IMG_0708-rev.JPG; IMG_0709-rev.JPG;

IMG_0711-rev.JPG; IMG_0713-rev.JPG; IMG_0716-rev.JPG

John,

Good afternoon. Thanks again for taking the time to walk the project site with me this morning. As we discussed, I have attached a memo outlining the findings of this morning's walk. The immediate actions that are recommended consist of removal of existing log piles and installation of a stone blanket along an apparent discharge point in the soil berm. After this morning's visit, I spoke with Robert who advised that the stone piles that he has on site are indigenous stone that he obtained from a neighboring home (the Witte home). He said that he was very excited to have obtained the stone and is very much looking forward to utilizing it in whatever restoration plan is accepted by the Village. I therefore omitted the removal of the stone piles from my memo. I trust that this modification is acceptable.

I advised Robert to contact you to discuss the scheduling of the log removal and stone blanker installation. I will be in contact with you once the topographic mapping is completed. If you have any questions in the meantime, please do not he sitate to contact me.

Best regards,

David Higgins, P.E.

Lanc & Tully Engineering and Surveying, P.C. P.O. Box 687 Route 207 Goshen, NY 10924 Phone- (845) 294-3700 Fax- (845) 294-8609

Lanc & Tully Engineering and Surveying, P.C.

P.O. Box 687, Route 207 Goshen, NY 10924 Phone (845)294-3700 Fax (845) 294-8609 E-Mail eng@lanctully.com

Memo

To: Robert Zgonena

From: David Higgins, P.E.

Date: December 26, 2012

Re: Site Visit with John Ledwith

As you are aware, at its December 18, 2012 meeting, the Village of Tuxedo Park Board of Architectural Review set a requirement that an evaluation for immediate soil and erosion control measures was to be made and that any resulting recommendations for these measures be installed by December 28, 2012. Accordingly, today I met at your property with John Ledwith to review and evaluate the conditions and to identify recommended remedial action in that regard.

Overall, although the area that has been recently filled lacks significant vegetation, the site is fairly stable due to the recent snowfall and freezing temperatures. The fill material appeared to be fairly loosely placed with a very uneven, undulating surface. Based upon the uneven surface, it appeared that during periods of rain, the surface likely provides some measure of storage where puddles and ponding may occur. There is a soil berm along the base of the fill that would also act to help detain the discharge of surface runoff during rain events. It was observed that there is a low area along this soil berm where it appears runoff may collect and discharge downhill (towards the area of a green treehouse) on a neighboring property. In order to help minimize any potential erosion at this point, it is recommended that it be stabilized with stone 6 to 12 inches in size from the top of the berm to the low point of the fill with a blanket width of at least 8 feet.

Additionally, the site has some piles of large logs in the vicinity of the lower driveway entrance that should be removed. John Ledwith advised that these logs should be relocated somewhere outside of the Village.

With regards to the installation of silt fence, I see little value in the placement of silt fence until such time as the limits of the property are identified and a long-term grading plan has been prepared by this office and reviewed and accepted by the Village of Tuxedo Park. Our office has completed the field work necessary for the boundary determination and topographic mapping of this area of the site and should have a map completed for submittal to the Village by January 8, 2012, as required by the B.A.R. Once the boundary line and grading plan has been established, the location of siltation fence and any other measures to be taken shall be identified and implemented.

Photographs of the site taken during the visit are included for reference.

You should contact John Ledwith at your earliest convenience to discuss your schedule for the removal of the logs and the installation of the stone stabilization. Please call me if you have any questions.

John Ledwith

Yanker Propone

From:

John Ledwith [jledwith@tuxedopark-ny.gov]

Sent:

Monday, January 07, 2013 11:36 AM

To:

'info@yankeepropane.com'

Subject:

Tuxedo Park - 54 East Lake Stable Rd.

Marla:

The tanks are located behind the garage and they are labeled Yankee Propane. You said that you have no reference of the current owners name, Glen Cavada, 54 East Lake Stable Rd., Tuxedo Park, NY. Check the prior owners last name, Economides.

Please have the tanks picked up at your earliest convenience.

Thank you.

Regards, John Ledwith Building Inspector

From: John Ledwith [mailto:jledwith@tuxedopark-ny.gov]

Sent: Friday, January 04, 2013 2:04 PM

To: 'info@yankeepropane.com'

Subject: Tuxedo Park - 54 East Lake Stable Rd.

Please be advised I have seen two of your propane tanks located behind a garage located at 54 East Lake Stable Rd. (Glenn Cavada). Confirm if these tanks are in use, and if not, have them removed from the property by January 31st.

If you have any questions, or need to speak with me, I can be reached at 351-4745 ext. 11.

Regards, John Ledwith Building Inspector

VILLAGE OF TUXEDO PARK P.O. BOX 31 80 LORILLARD ROAD TUXEDO PARK, NEW YORK 10987

January 16, 2013

Mr. Uli Pendl 12 Ridge Road Tuxedo Park, NY 10987

Re:

Parcel No. 108-1-2

Fallen Trees - Ridge Road & Pepperidge Road

Dear Mr. Pendl:

As per our earlier discussions, the fallen trees on your property need to be removed. Please provide me with a date that the trees will be removed at your earliest convenience.

Thank you for your cooperation with resolving this matter.

Very truly yours,

John C. Ledwith IV Building Inspector

VILLAGE OF TUXEDO PARK P.O. BOX 31 80 LORILLARD ROAD TUXEDO PARK, NEW YORK 10987

January 16, 2013

Mr. Dong Xu 147 Tower Hill Loop Tuxedo Park, NY 10987

Re: Par

Parcel No. 106-1-21

Fallen Tree - Tuxedo Road

Dear Mr. Xu:

A few weeks ago I left you a voice mail message regarding a tree that had fallen during hurricane Sandy that is very close to Tuxedo Road. In accordance with the Village Code, any hazardous trees within 50' from the property line must be removed.

As it has been over a month since the tree has fallen, please have the tree removed within the next 14 days.

Thank you for your cooperation with resolving this matter.

Very truly yours,

John C. Ledwith IV Building Inspector

VILLAGE OF TUXEDO PARK P.O. BOX 31

80 LORILLARD ROAD TUXEDO PARK, NEW YORK 10987

Date: January 18, 2013

To: Joseph Perez

From: John Ledwith, Building Inspector

Re: Parcel No. 106-1-38.1

§ 75-9. Exterior maintenance standards.

[Amended 2-21-1990 by L.L. No. 1-1990]

The exterior of all premises shall be kept free of the following matter, materials or conditions:

- A. Refuse, as hereinabove defined.
- B. Rubbish, as hereinabove defined.
- <u>C.</u> Construction materials.
- <u>D.</u> Abandoned, uncovered or structurally unsound wells, shafts, towers, chimneys, exterior cellar openings, basement hatchways, foundations or excavations.
- <u>E.</u> Abandoned iceboxes, refrigerators, boilers, hot-water heaters, television sets and other similar major appliances.
- F. Nuisances, as hereinabove defined.
- <u>G.</u> Vehicles or parts thereof, including boats and trailers, motorized or not, licensed or unlicensed, registered or unregistered, which vehicles or parts thereof are or have been junked, abandoned, dismantled or are in a state of visible disrepair.

<u>H.</u> Fallen trees, limbs or branches within 50 feet of a public roadway or neighboring property line.

I. Deteriorated fences.

VILLAGE OF TUXEDO PARK

P.O. BOX 31 80 LORILLARD ROAD TUXEDO PARK, NEW YORK 10987

January 11, 2013

Mr. Oliver Grace Tuxedo Park Estates, LP 55 Brookville Road Glenhead, NY 11545-0163

Re: Parcel No. 108-1-9.22

Fallen Trees - Tuxedo Rd. & Pine Hill Rd.

Dear Mr. Grace:

Several weeks ago I left you a voice mail message regarding some trees that had fallen during hurricane Sandy that are very close to the Village Roads. In accordance with the Village Code, any hazardous trees within 50' from the property line must be removed.

Please have someone from your office contact me to coordinate removal of the trees by the end of this month.


Thank you for your cooperation with resolving this matter.

Very truly yours

John C. Ledwith IV Building Inspector

App	lication No Permit No. July 21, 2010
	Building Department VILLAGE OF TUXEDO PARK County of Orange
	No.: Section . 107 Block 1 Lot 67
Nº	Certificate of Occupancy
	Date January 18 , 2013
Permit Buildi law. Th	approved plans and specifications heretofore filed in this office with Application for Building t dated . July 21, 2010, pursuant to which ng Permit was issued, and conforms to all of the requirements of the applicable provisions of the ne occupancy for which this certificate is issued is . \$\frac{9}{2}\$\$ \$\frac{9}
The cer of the a	rtificate is issued to .John King. & Douglas Duchin
	The Certificate of Occupancy will be issued only after affidavits or other competent evidence is submitted to the Superintendent of Buildings that the completion of the construction in compliance with the State Building Construction Code and with other laws, ordinances or regulations affecting the premises, and in conformity with the approved plans and specifications. A final electrical, plumbing, heating or sanitation certificate or other evidence of compliance may be required before the issuance of the Certificate of Occupancy,
	This Certificate of Occupancy only attests as to the legal use and occupancy under the zoning law and does not certify as to compliance with all of the requirements of the Building Codes effective this date.
· n	Roard of Trustees approved on 6th

ISARE CELENBROWN 3 ACOMA ROS.



INCORPORATED 1952 (845) 351-4745 (Voice) (845) 351-2668 (Fax) Website: tuxedopark-ny.gov

VILLAGE BOARD MEETING FOURTH TUESDAY OF EACH MONTH

VILLAGE OF TUXEDO PARK

P.O. BOX 31 80 LORILLARD ROAD TUXEDO PARK, NEW YORK 10987

Date: January 9, 2013

To: John Ferraro

Susan Niblo

From: John Ledwith, Building Inspector

Re: Niblo – Framing Inspection

50 Cliff Rd.

Parcel No. 106-1-65

As per my site inspection this morning, the following areas have <u>not</u> been framed in accordance with the approved plans:

- 1. Right Side Elevation, Sheet A-5
 - a. Deletion of a window located on the side of the garage.
 - b. Change in window size and addition of one window at the rear of the house.
 - c. Changes to dormer above letter b.
- 2. Left Side Elevation, Sheet A-5
 - a. Change in roof height at ridge. Left side of ridge higher than right side of ridge.
 - b. Deletion of window in area noted as office.

The above noted items deviate from the plans approved by the Board of Architectural Review.

Please advise me within 48 hours of your plans to correct these items.

John Anthony Ferraro PC A R C H I T E C T 25 Jodi Lane

New City, New York 10956 Tel: 845-624-0758 Fax: 845-624-2163

www.johnferraroarchitect.com

January 10, 2013

Board of Architectural Review Village of Tuxedo Park P.O. Box 31 Tuxedo Park, New York 10987

Re:

Niblo Residence Field Revisions

Distinguished Board members,

In response to John Ledwith's letter dated January 9, 2013 I submit the following drawings which indicate the areas in which we seek approval. The areas are clouded and correspond to the item numbers in John's letter.

CLERK'S OFFICE

The following explains the reason for the requested changes:

1a. In an effort to increase the security of the property the Niblo's chose to remove the window in the rear of the garage.

1b. After consultation with Marvin Windows it was decided that 5 smaller windows would work better with the interior design of the kitchen rather than 4 larger ones. The Marvin architectural team assisted making the scale of the mullions more architecturally pleasing. We were careful to maintain the existing rough opening as close as possible to minimize the exterior effect. These windows are already purchased. It would be much appreciated if this was approved.

1c. On 1/3/13 I arrived on site to find the dormer in bedroom #2 was being framed differently than on the plans. Sue and I referred back to the original plans approved by the BAR and asked the workers to stop construction on that specific spot until we notified inspector. If the Bar wishes us to return to as originally planned we will do so. Otherwise, to avoid delays, we will finish in a way that is suitable to all.

2a. The framers submitted, to the owner and I, a change to the ridge line on the left side of the house that would allow for a true hip turn and a continuous roof slope from the front to the rear. Additionally, the difference between the top plate heights between the family room and the master suite result in the lower soffit line in the rear. The priority of this change was to maintain the proportions of the front elevation approved by the BAR. Photographs attached.

2b. After seeing the windows framed out it is was agreed the stained glass looked better in a continuous line rather than separated in the room.

We would also like to request the following changes in the rear elevation:

Window sizes in the Master Bedroom. The new R.O. is 53" x 60" in lieu of the original size, 53" x 50", shown on the rear elevation. The taller windows are more proportionate with the ceiling height and soffit line.

French Door Locations in the Family Room. The owner prefers the center line of the doors align with the center line of the trusses above.

Thank you for your consideration in this matter.

Respectfully,

John Verraro RA, NCARB

*** FAX TX REPORT *** *******

TRANSMISSION OK

JOB NO.

1974

DESTINATION ADDRESS

5773477

PSWD/SUBADDRESS

DESTINATION ID

ST. TIME

01/17 10:46

USAGE T

00'51

PGS.

1

RESULT

OK

* Adda I Tem Not ON Form FAXED YESTERDAY

Orange & Rockland

Streetlight Repair Request Form

Orange and Rockland Utilities, Inc., 390 West Route 59, Spring Valley, NY 10977

Contact Name: JOHN C. LEDWITH TY DEPG. INSP. TOWN/VIllage/Borough: VILLAGE OF TUXGOO PARK, NY Telephone Number: 845-351-4745 x, 3

Please Fax to: Electric Operations - Northern Division

845-577-3477

Questions should be directed to Customer Assistance at 1-877-434-4100.

10 Digit Pole Number	Closest House Number	Street Name, City, State	9	Closest Cross Street	Additional information (Fight out, aways onlot, broken place)	O&R Use Only
5 3914 43574	Nohouse	Tuxealo Rel.		Before Pine Rd.	Cight out, atrass aniat, proton classes	our sse only
33875 43597	Nohoure	Tuxado Rol.		Pine Rd.	Cight out	
45375D 48665	Nohaze	Toxedo Rd. Toxedo Rd.		Papperiole &	Cight out	
53679 43985	Tixedo	Across From Ent	Travce	Corilland for		
		To Toxedo Ola	ib			
		\$3457 478 80			/	
		526 VY Exc 8 ->				
53440 43242	32 Acons	Asomo Rd.		E.Colce	Cishtout	
AIR to so on a						
MR-10-28-08.0						

0809-0075R

VILLAGE OF TUXEDO PARK P.O. BOX 31 80 LORILLARD ROAD TUXEDO PARK, NEW YORK 10987

Date: January 11, 2013

Sent via Fax – Page 1 of 4

914-925-9280

To: Ralph, Orange & Rockland Customer Service

From: John Ledwith, Building Inspector

Re: Removal of Electrical Service located at 1 Tuxedo Rd.

Account Number 97626-89000 Meter Number 601000056

As per your request:

1. See the attached document from the County of Orange that indicates that the Village of Tuxedo Park owns the property at 1 Tuxedo Rd. I have also included a copy of the last utility bill that we received.

- 2. Pole number 54040/43550 is where the electric service drop is located. This needs to be disconnected.
- 3. The color of the building is grey stone with green trim. Pictures of the building are included.
- 4. The nearest cross street is NYS Route 17.

Please contact me if you have any questions, and to notify me in advance of performing the work.

I can be reached at 351-4745 ext. 11 or via email at <u>iledwith@tuxedopark-ny.gov</u>.





Navigation Tax Maps | ORPS Links

Help Log In

Residential
_
Property Info
Owner/Sales
Inventory
Improvements
Tax Info
Report
Comparables

Commercial	
Property Info	
Owner/Sales	
Inventory	
Improvements	
Tax Info	
Report	
Comparables	

SWIS:	3350	01	Tax ID	:	108-	1-12	
		Tax I	Map ID /	Property	Data		
Status:		Active		Roll Section	n:	Wholl	y Exem
Address:		1 Tuxe	do Rd				
Property (Class:	210 - 1 Res	. Family	Site Proper Class:	ty	662 -	Police/fir
Site:		Res 1	~~~	In Ag. Dist	rict:	No	
Zoning Co	de:	-		Bldg. Style	:	Old S	tyle
Neighborh		00005	-	School Dist	rict:	Tuxed	О
Legal Prop Descriptio		Legal d	escription	not given fo	r prope	rty	
Total Acreage/S	ize:	1.00		Equalizatio Rate:	n		
Land Asse	ssment:	2012 -	\$24,000	Total Asses	sment:	2012	- \$60,000
Full Marke Value:	et	2012 -	\$369,200				
Deed Book	(;	2028		Deed Page:		540	
Grid East:		578444	1	Grid North:		86048	39
Bank Code	2;	N/A					
		Spe	cial Dist	ricts for 2	012		
	scription	1	Units	Percen	t	Туре	Value
Tux joint f	ire		0	0%		W. T. W.	0
			Land	Types			
		Туј	эе			S	lze
Undevelor	ned				I	1 40	acres

Photographs No Photo Available

Pictometry LiveLink
View this property's
Pictometry imagery in
LiveLink.

Documents

No documents found for this parcel

View Tax Map
View in Google Maps
View in Yahoo! Maps
View in Bing Maps
Map Disclaimer

E 12/05/12
BILLING SUMMARY

BILLING DATE

Payments: 11/21/12

TOTAL AMOUNT DUE

11/02/12

Service Charges Electric

ACCOUNT NUMBER 97626-89000 Last Bill

\$242.75

-96.17


70.09

\$70.09

-146.58



VILLAGE OF TUXEDO PARK 1 TUXEDO RD, TUXEDO PARK, NY 10987 POLICE BOOTH & KEEPPOLICE STATION



If you have questions about this bill, call toll-free 1-877-434-4100 or go to www.oru.com

ELECTRIC SMALL C& Meter Number: 601000	I GEN SERV S	SEC- DELIVER	Υ	
Nov 29 reading (Actual) Oct 29 reading (Estimate)	<i>y</i>	DEMAND 59.92 -59.70	ENERGY 20553 -20534	
Meter reading difference Meter multiplier		0.2 x 12	19 x 12	•
Total Usage 31 Days		2.6 KW	/ 228	KWH
Delivery Charges Basic Service Charge First First Energy Cst Adj SBC/RPS Chg RDM Adjustment Transition Adj Chg NY Assessment Government surcharges -	2.6 KW 228 KWH @ 228 KWH @ 228 KWH @ 228 KWH @ 228 KWH @ 228 KWH @	-0.00200¢ 0.48400¢ -0.27700¢ 0.01100¢		\$18.00 1.30 11.69 .00 1.10 63 .03 .75
Total Delivery Charges				\$32.30
Metering Charge Government surcharges - Total Metering Charge	•			14.39 .03 \$14.42
Total Supplier Charge				23.37
CURRENT ELECTRIC	CHARGES		g in gelt a gedad. En gradefallen sig	\$70.09

ECEIVE

O&R certifies that the amount of \$70.09 is correct, that items, services & disbursements charged were rendered as stated and no part has been paid or satisfied. Exempt taxes are excluded and the amount claimed is due on 12/31/2012.

MANAGER CUSTOMER ACCOUNTING CHRISTINE MARCO

To avoid a 1.5% late charge, please pay by 12/31/2012. Allow 2 business days for payments to post to your account.

We offer convenient payment options such as pay by phone, pay online or in person at Rockland Pawn Brokers Inc, 86 Rte 59, Spring Valley

Your alternate energy supplier for the billing period was Hudson Energy Services LLC. They can be contacted at 1-877-HUDSON9.

Have your payments electronically deducted from your bank account by enrolling in Automatic Bill Payment. Place an X in the box on your bill stub. Details at www.oru.com/ABP

почение иноиди магоглисацију зеазоп.

Gas Supply Charge reflects the monthly charges the company pays for purchasing gas supply on behalf of full service customers


Government Surcharges include New York State and local taxes, such as the Gross Receipts Tax, and local village taxes, where applicable.


energy supplier for which the company provides billing services.

NY Assessment recovers fees imposed by the state as authorized under Section 18-a of the Public Service Law.

SBC/RPS Charge: System Benefits Charge recovers the cost of mandated energy efficiency, environmental protection and low income assistance programs. The Renewable Portfolio Standard (RPS) is included in this charge to recover the cost of renewable resources programs.







John Ledwith

YALOO FENCE

From: John Ledwith [jledwith@tuxedopark-ny.gov]

Sent: Monday, January 14, 2013 9:22 AM

To: 'Carlos Marin'

Cc: 'dmatthews@tuxedopark-ny.gov'; 'jvoss@tuxedopark-ny.gov'

Subject: Village of Tuxedo Park - Invoice Review request

Attachments: Dec 2012 Invoice \$3985.pdf; Nov 2011 Invoice \$1050.pdf

Carlos:

Please forward this matter to Elaine Gedeiko.

Attached are two invoices for similar work performed by Yahoo Fence Co. Can you explain to me why the invoice dated 11/2011 was for \$1,050 and the invoice dated 12/2012 was considerably higher at \$3,985. Additionally, some of the materials used in the repair in December were obtained by Yahoo Fence at no cost from the Village, and the payroll sheet attached to the invoice shows that no more than 2 hours was spent on side.

The Village of Tuxedo Park is happy with the guiderail that your company installed for us just a few years ago, but the recent invoice in the amount of \$3,985 requires review.

Upon resolution of this matter the invoice will be paid.

Regards, John Ledwith Deputy Clerk & Treasurer

From: Carlos Marin [mailto:cmarin@vaboofence.com]

Sent: Friday, December 07, 2012 3:30 PM

To: 'John Ledwith'

Subject: RE: Tuxedo Park, guardrail repair

Hi John just confirming that we are sending our guys on Monday the 10 to do the guide rail repair, the crew should be there between 9am and 10am any questions please email or call me

Thanks

Carlos Marin Yaboo Fence Company (845)358-0118 Fax:(845)358-7342

From: John Ledwith [mailto:jledwith@tuxedopark-ny.gov]

Sent: Tuesday, December 04, 2012 1:35 PM

To: 'John Ledwith'; 'Carlos Marin' **Cc:** darin@yaboofence.com

Subject: RE: Tuxedo Park, guardrail repair

Do you know when the repairs below have been scheduled to be made?

John Ledwith

Invoice Date

Invoice #

INVOICE

95 West Nyack Way West Nyack, NY 10994 11/16/2011

11-1116-896

Job At:

Repair damaged rails.

Phon..(845) 358-0118

Fa... (845) 358-7342

Bill To:

Village of Tuxedo Park 80 Lorillard Rd PO Box 31 Tuxedo Park, NY 10987

PLEASE PAY

THIS AMOUNT

\$1,050.00

Make checks payable to: Yaboo Fence Company, Inc.

Please check box if address is incorrect or has changed, and indicate change(s) on reverse side.

Have E-Mail? Please write it here:

Yaboo Fence Company, Inc.

PLEASE DETACH AND RETURN TOP PORTION WITH PAYMENT

95 West Nyack Way West Nyack, NY 10994

	Telephone No. (845) 351-4745 x11	Terms	Due 1		Rep MGJ
Qty	Description	Ra	ate	Aı	mount
	Supply Materials and Labor to Install: 2 damaged rails from new guide rail: Need 1 new post bolt 16 Splice plate bolts 3 Splice plates		1,050.00		1,050.00

There will be a \$30.00 charge for all returned checks. 1 1/2% interest will be assessed on all unpaid balances after 30 days.Reasonable attorney's fees, cost & disbursements in the

Billing Inqueries?... (845) 358-0118

Subtotal	\$1,050.00
Sales Tax (8.375%)	\$0.00
Total	\$1,050.00
Payments/Credits	\$0.00
Balance Due	\$1,050.00

Yaboo Fence Company, Inc.

Invoice Date

Invoice # 12-1210-172

INVOICE

95 West Nyack Way West Nyack, NY 10994 12/10/2012

Job At:

Tuxedo Rd. Tuxedo Park

Phon...(845) 358-0118

Fa... (845) 358-7342

Bill To:

Village of Tuxedo Park 80 Lorillard Rd PO Box 31 Tuxedo Park, NY 10987

PLEASE PAY

\$3,985.00

Make checks payable to: Yaboo Fence Company, Inc.

Please check box if address is incorrect or has changed, and indicate change(s) on reverse side.

Have E-Mail? Please write it here:

THIS AMOUNT

Yaboo Fence Company, Inc.

PLEASE DETACH AND RETURN TOP PORTION WITH PAYMENT

95 West Nyack Way West Nyack, NY 10994

		Telephone No. 845-351-4745 x 11	7	Terms	Due 1 12/10/		Rep DM
Qty	Desc	ription		Rat	e	A	mount
	Supply Material and Labor Repair existing guardrail d Reset one post (re using ex Replace one rail (rail to be Reassemble with new bolts	amaged by storm. isting post) provided by owner).		3	3,985.00		3,985.00
			posterior de la constante de l	DEC	OF TUXEDO N	PARK	

There will be a \$30.00 charge for all returned checks. 1 1/2% interest will be assessed on all unpaid balances after 30 days.Reasonable attorney's fees, cost & disbursements in the event of non-payment.

	Subtotal	\$3,985.00
f	Sales Tax (8.375%)	\$0.00
	Total	\$3,985.00
	Payments/Credits	\$0.00
	Balance Due	\$3,985.00

Billing Inqueries? ... (845) 358-0118

U.S. Department of Labor Employment Standards Administration Wage and Hour Division

PAYROLL

(For Contractor's Optional Use; See Instructions, Form WH-347 Inst.)
Persons are not required to respond to the collection of information unless it displays a currently valid OMB control number.

NAME OF CONTRACTORX JOR SUBCONTRACTOR [Yaboo Fence Company, Inc.	R SUBCON	ITRACTOR[]		Ā	ADDRESS		West Ny st Nyac	95 West Nyack Way West Nyack, NY 10994	13 1994		TO THE PARTY OF TH		OMB No	OMB No.: 1215-0149	
PAYROLL NO. 7	FOR WE	FOR WEEK ENDING 12/11/2012		RIZ	PROJECT AND LOCATION VIII. of Tuxedo Park	AND LC	CATIO	1	orillard I	80 Lorillard Road Tuxedo Park, NY 10987			PROJECT C Tuxedo Roa	PROJECT OR CONTRACT NO. Tuxedo Road Guide Rail	T NO.
(1)	٢	2) (3)		4)	(4) DAY AND DAT	ND DAT	Ц			(5) (6)		((8)		Ó
			WED	THC	FRI	SAT	SUN	MON	TUE			È	2)		NE (a)
NAME, ADDRESS, AND SOCIAL SECURITY NUMBER		WORK CLASSIERCATION	12/5	12/6	127	12/8	12/9	12/10 1:	12/11	OTAL		GROSS			WAGES
OF EMPLOYEE				HOU	HOURS WORKED		EACH DAY	44		HOURS RA	RATEOF PAY	EARNED	DEDUCTIONS	SNC	WFFK XFFK
Shane Patrick Hovorka 75 Burrows Lane Blauvelt, NY 10913 000-00-6662		0 laborer oc S	R 0.00	0.00	0.00	00.00	0.00	2.00 0	0.00	2.00	55.00	110.00	FICA W/H TAX OTHER Total:	6.22 7.00 0.55 13.77	96.23
Anthony J Laconte 1265 Williams Drive Shrub Oak, NY 10588 000-00-9800	,	laborer oc	R 0.00	0.00	0.00	00.00	0.00	2.00	0.00	2.00	55.00	110.00	FICA Total:	6.22	103.78
Claudio Lopez 37 M Madison Ave Spring Valley, NY 10977 000-00-4820	N V Plans	2 laborer oc M	R 0.00	00.00	0.00	0.00	0.00	2.00	0.00	2.00	55.00	110.00	FICA Total:	6.22	103.78
We estimate that it will take an average of 56 minutes to complete this collection of information, including time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. If you have not considered and completing and reviewing the collection of information.	average of 5	56 minutes to complete this control and reviewing the collection	collection	of inform	nation, il	ncluding	time fo	r review	ing inst	ructions, sea	arching existi	ing data so	urces, gatheri	ing and	

maintaining the data meeded, and completing and reviewing the collection of information. If you have any comments regarding these estimates or any other aspects of this collection of information, including suggestions for reducing this burden, send them to the Administrator, Wage and Hour Division, ESA. U.S. Department of Labor, Romm N3502, 200 Constitution Avenue, N.W., Washington, D.C. 20210.

For Hours Worked; R=Regular O=Overtime D=DoubleTime T=TripleTime FORM WH-347, Revised Nov. 1996 - FORMERLY SOL 184 *** Produced by PEM Software Systems, Ltd. 800-803-1315

Village of Tuxedo Park Processed Water Analysis

2000-2012 Water **Processed** Water Billed Year **Ouarter** Water Loss **Percent Loss** 2012 04 34,000,300 12,945,930 21.054.370 -62% 2012 Q3 41,710,000 24,643,610 17,066,390 -41% 2012 37,046,000 O_2 16,471,170 20,574,830 -56% 2012 29,898,000 Q1 18,821,700 11,076,300 -37% 2011 Q4 28,109,000 13,481,370 14,627,630 -52% 2011 Q3 33,896,000 20,401,230 13,494,770 -40% 2011 Q2 29,605,000 15,490,880 -48% 14,114,120 2011 Q1 24,881,000 12,936,359 11,944,641 -48% 2010 Q4 27,577,000 16,144,060 11,432,940 -41% 2010 Q3 37.607,000 22,073,480 15,533,520 -41% 2010 Q2 28,555,000 16,248,890 12,306,110 -43% 2010 26,486,000 10,699,340 -60% Q1 15,786,660 2009 04 23,092,000 12,787,710 10,304,290 -45% 2009 Q3 31,207,000 14,459,420 16,747,580 -54% 2009 12,617,160 Q2 30,098,000 17,480,840 -58% 2009 Q1 23,678,000 9,425,790 -60% 14,252,210 2008 Q4 24,419,000 10,975,170 13,443,830 -55% 2008 Q3 30,655,000 19,921,180 10,733,820 -35% 2008 O_2 27,627,000 13,706,780 13,920,220 -50% 2008 Q1 20,515,000 10,967,110 9,547,890 -47% 2007 04 -39% 24,558,000 14,947,340 9,610,660 2007 Q3 37,987,000 18,286,770 19,700,230 -52% 2007 Q2 34,482,000 23,387,975 11,094,025 -32% 2007 Q1 27,834,000 -33% 18,603,955 9,230,045 2006 **O**4 25,793,000 10.284,265 15,508,735 -60% 2006 Q3 31,680,000 16,072,170 -49% 15,607,830 2006 Q2 27,274,000 13,751,420 13,522,580 -50% 2006 Q1 21,291,000 12,715,630 8,575,370 -40% 2005 28,794,000 10,423,020 Q4 18,370,980 -64% 2005 Q3 40,110,000 18,388,080 21,721,920 -54% 2005 O238,186,000 17,561,800 -54% 20,624,200 2005 Q1 33,838,000 11,197,750 22,640,250 -67% 2004 Q4 33,602,000 12,076,680 21,525,320 -64% 2004 Q3 37,594,000 16,403,070 21,190,930 -56%

16,054,440

24,685,730

14,107,950

16,020,680

12,853,365

9,980,720

19,084,560

12,227,270

14,666,050

16,020,680

12,641,635

12,768,280

2004

2004

2003

2003

2003

2003

Q2

Q1

Q4

Q3

Q2

01

35,139,000

36,913,000

34,054,000

25,495,000

22,749,000

28774000

-46%

-67%

-49%

-53%

-50%

-44%

^{*} Started to include "Non-Billable Consumption" in water billed to reflect usage at water & sewer plants.

Village of Tuxedo Park Processed Water Analysis 2000-2012

		2000-2012			
Year	Quarter	Water Processed	Water Billed	Water Loss	Percent Loss
2002	Q4	22261000	15,230,834		
2002	Q3	30,285,000	16,571,100		-45%
2002	Q2	24,826,000	14,076,593	10,749,407	-43%
2002	Q1	21,881,000	13,400,992	8,480,008	-39%
2001	Q4	21,594,000	12,305,130	9,288,870	-43%
2001	Q3	27,451,000	17,733,870	9,717,130	-35%
2001	Q2	33,120,000	15,091,297	18,028,703	-54%
2001	Q1	24,925,000	13,745,000	11,180,000	-45%
2000	Q4	25,441,000	10,489,990	14,951,010	-59%
2000	Q3	32,767,000	25,583,315	7,183,685	-22%
2000	Q2	34,700,000	14,021,444	20,678,556	-60%
2000	Q1	34,498,000	14,305,585	20,192,415	-59%
			Maximum	2005-Q1	-67%
			Minimum	2000-Q3	-22%
			Average		-49%