

6

**VILLAGE OF TUXEDO PARK**  
P.O. BOX 31  
80 LORILLARD ROAD  
TUXEDO PARK, NEW YORK 10987

**DPW Report**  
**September 21, 2021 to October 22, 2021**

**Roads**

1. Installed plywood and cedar shakes on the corners of the Police Booth.
2. Installed new mailbox stand on Continental Road.
3. Cleaned drains and catch basins.
4. Removed fallen tree at the south end of Tuxedo Lake.
5. Weed-whacked East Lake Road.
6. Finished installing stone border around triangle at West Lake Road and Brook Road.
7. Removed barberry bushes and cleaned up debris at the south end of Tuxedo Lake.
8. Weed-whacked around Ridge Road and Potuckit water storage tanks.
9. Installed bullet proof widows at the Police Booth.
10. Temporarily installed bollards around Police Booth.
11. Installed base trim and entry door at the Police Booth and installed bullet proofing on door.
12. Installed 8" insertion valve on water main on East Lake Road.
13. Worked with O&R tree crew removing dangerous trees on Laurel Road.
14. Removed fallen tree on East Lake Road at triangle.
15. Installed a reflective post on Eagle Mountain Road.
16. Removed rhododendron and mountain laurel from triangle at Turtle Mountain Road.
17. Patched Chastellux Lane ahead of repaving.
18. Weed-whacked Wee Wah and Pond #3 dams.
19. Worked with Sterling Carting on bulk pick-up.
20. Trimmed back brush on Turtle Point Road ahead of grinding and paving.
21. Installed new drain pipes on West Lake Road ahead of grinding and repaving.

**Water**

1. Repaired a water leak on Stable Road.
2. Installed a new 6" water valve to replace the leaking existing valve on East Lake Road.
3. Continued doing 3<sup>rd</sup> quarter water meter reading.
4. Had annual health Department inspection of the Water Plant.
5. Greased pumps and motors at the Water Plant.
6. Marked out water main on East Lake Road.
7. Turned off water at the Riken residence for installation of meter pit and turned water back on.

**Sewer**

1. Performed daily maintenance at the Sewer Plant.
2. Had annual inspection of the Sewer Plant by the DEC.
3. Repaired a leak on the chlorine line at the Sewer Plant.
4. Did bi-monthly sampling at Sewer Plant.
5. Had flow meters calibrated at the Sewer Plant.
6. Prepared and mailed monthly sewer report to the DEC.