INCORPORATED 1952 (845) 351-4745 (Voice) (845) 351-2668 (Fax) Website: tuxedopark-ny.gov

VILLAGE OF TUXEDO PARK

P.O. BOX 31 80 LORILLARD ROAD TUXEDO PARK, NEW YORK 10987

DPW Report December 10, 2021 to January 17, 2022

Roads

- 1. Planted holly bushes in new median at the Front Gate
- 2. Picked up leaves throughout the Village
- 3. Installed wiring conduit for the EZ Pass system at Main Gate
- 4. Blew leaves from triangles
- 5. Removed trash rack and opened outlet gate at the Wee Wah dam for the winter
- 6. Sanded and repainted Police Headquarter sign
- 7. Installed new mailbox stands at Tower Hill Loop and Turtle Mountain
- 8. Worked on building more mailbox stands
- 9. Picked up Christmas trees throughout the Village
- 10. Worked on plow equipment
- 11. Cut brush
- 12. Plowed and salted roads on 12/21/21, 1/7/22, 1/9/22, 1/16/22, and 1/17/22
- 13. Received and put into storage shed 163 tons of salt
- 14. Washed and cleaned all trucks after plow/salt operations
- 15. Installed new wall heater at the Mountain farm pump station

Water

- 1. Did 4th quarter meter readings
- 2. Did various meter readings and final readings requested by Denise
- 3. Filled chemical crocks as needed
- 4. Did daily and monthly sampling
- 5. Hach Co. serviced chlorine and turbidity analyzers
- 6. Did various water and sewer mark-outs for Dig Safe NY
- 7. Replaced frozen and broken meter at Colwell residence
- 8. Checked that heat was working in all buildings
- 9. Turned off water to 18 Pepperidge Road for water line replacement
- 10. Prepared and sent monthly report to the Health Department
- 11. Replaced hose on chemical pump
- 12. Met with Trustee Kasker and various fire hydrants
- 13. Responded to Hempel residence after a call of no water; found line was frozen; thawed line with salamander heater
- 14. Responded to the Spangler residence after a call of a broken hose spigot; turned off
- 15. Responded to Colwell residence for a broken pipe in basement; turned off; second call in a week for frozen lines

<u>Sewer</u>

- 1. Installed new sludge pump in #1 clarifier at Sewer Plant
- 2. Checked the Turtle Point Road pump station regularly
- 3. Did daily maintenance and testing at the Sewer Plant
- 4. Had sludge removed from digesters
- 5. Prepared and sent monthly sewer report to the DEC
- 6. Performed bi-monthly compliance testing at the Sewer Plant
- 7. Drained, cleaned and performed maintenance to the chain and flight components on #1 clarifier
- 8. Cleared sewer blockage on East Lake Road
- 9. Greased pumps and equipment